




Model	Other model names	Document Name	Article No.	Date	Revision	Revision date
FX Typhoon and T12	Typhoon – Logun Solo, Tornado (JPN); F12- Tornado 5 (JPN)	Repair kit Typhoon / T12	7046	2020-03-19	-	-



D



F



NO	ART. NR	DESCRIPTION	NO	ART. NO	DESCRIPTION
11.1	5108	O-ring 5,28x1,78 PUR70	28	11624	O-ring 22 x 2,5 NBR70
13	5112	O-ring 5,28 x 1,78 NBR70	45	5104	O-ring 9,3 x 2,4
14	5112	O-ring 5,28 x 1,78 NBR70	46	16028	O-ring 12 x 1
15	2529	O-ring 4,3 x 1,5 NBR70	47	11624	O-ring 22 x 2,5 NBR7
16	7044	Valve Seat cpl.			
18	7034	Valve pin cpl.	D10	5107	O-ring 2,9x1,78 PUR90
22	18037	Valve spring lid 5,5	F2	11614	Washer
26+27	7045	Backvalve Complete	F3	5107	O-ring 2,9 x 1,78 PUR 90